


Photographic Log

Facility Name:		Site Location:	Project No.:
Park Avenue Hotel Group Tennessee LLC aka Athens Lodge, Red Roof Inn		115 CR-247 Athens, TN	TN0028886
Photo No.	Date		
1	3-30-2017		
Description Bing Maps capture of 115 CR-247 Athens, TN. The facility is currently known as Red Roof Inn & Suites. The red arrow indicates the location of the wastewater treatment plant at the end of the gravel access road.			

Photographic Log

Facility Name:		Site Location:	Project No.:
Park Avenue Hotel Group Tennessee LLC aka Athens Lodge, Red Roof Inn		115 CR-247 Athens, TN	TN0028886
Photo No.	Date		
2	3-30-17		
Description Red Roof Inn sign indicating new owners. Photo taken from the Red Roof Inn parking lot facing southwest.			

Photographic Log





Facility Name:		Site Location:	Project No.:
Park Avenue Hotel Group Tennessee LLC aka Athens Lodge, Red Roof Inn		115 CR-247 Athens, TN	TN0028886
Photo No.	Date		
3	3-30-2017		
Description Wastewater treatment plant. Photo taken from termination of gravel access road facing south.			

Photo No.	Date		
4	3-30-2017		
Description Wastewater treatment plant. Photo taken from outside the perimeter fence and gate facing south.			

Photographic Log

Facility Name:		Site Location:	Project No.:
Park Avenue Hotel Group Tennessee LLC aka Athens Lodge, Red Roof Inn		115 CR-247 Athens, TN	TN0028886
Photo No.	Date		
5	3-30-2017		
Description Breach in wastewater plant perimeter fencing. Photo taken from outside the perimeter fence on the east side of wastewater plant facing west.			
Photo No.	Date		
6	3-30-2017		
Description View of sludge basin/aeration basin divider wall and piping. Photo taken from inside the perimeter fencing facing south.			

Photographic Log






Facility Name: Park Avenue Hotel Group Tennessee LLC aka Athens Lodge, Red Roof Inn		Site Location: 115 CR-247 Athens, TN	Project No.: TN0028886
Photo No. 7	Date 3-30-2017		
Description Closer view of sludge basin/aeration basin wall and piping to show deterioration of structure piping and basin walls indicated by red arrows.			

Photo No.	Date	
8	3-30-2017	
Description		
Aeration basin. Photo taken from within the perimeter fencing on the west side of the basin facing east.		



Photographic Log

Facility Name:		Site Location:	Project No.:
Park Avenue Hotel Group Tennessee LLC aka Athens Lodge, Red Roof Inn		115 CR-247 Athens, TN	TN0028886
Photo No.	Date	Insert	
9	3-30-2017		
Description Clarifier basin with visible floating solids. The photo was taken from inside the perimeter fencing from the west side of the basin facing east.			
Photo No.	Date	Insert	
10	3-30-2017		
Description Deterioration of piping between clarifier basin and chlorine contact chamber basin indicated by red arrow. Photo taken from within the perimeter fencing on west side of the basin facing east.			





Photographic Log

Facility Name:		Site Location:	Project No.:
Park Avenue Hotel Group Tennessee LLC aka Athens Lodge, Red Roof Inn		115 CR-247 Athens, TN	TN0028886
Photo No.	Date		
11	3-30-2017		
Description Closer view of deterioration of piping between clarifier basin and chlorine contact chamber basin. Photo taken from within the perimeter fencing on west side of the basin facing east.			
Photo No.	Date		
12	3-30-2017		
Description Deterioration of outer wall of chlorine contact chamber basin indicated by red arrow. Photo taken from within the perimeter fencing on west side of the basin facing east.			



Photographic Log

Facility Name:		Site Location:	Project No.:
Park Avenue Hotel Group Tennessee LLC aka Athens Lodge, Red Roof Inn		115 CR-247 Athens, TN	TN0028886
Photo No.	Date		
13	3-30-2017		
Description Closer view of deterioration of the outer wall of chlorine contact chamber basin. Photo taken from within the perimeter fencing on west side of the basin facing east.			
Photo No.	Date		
14	3-30-2017		
Description East wall of clarifier basin. Soil is eroded under the basin indicated by red arrows. Photo taken from inside perimeter fencing facing southwest.			

Photographic Log

Facility Name:		Site Location:	Project No.:
Park Avenue Hotel Group Tennessee LLC aka Athens Lodge, Red Roof Inn		115 CR-247 Athens, TN	TN0028886
Photo No.	Date		
15	3-30-2017		
Description Close up of eroded areas under the wall of clarifier basin. Photo taken from inside perimeter fencing from east facing west.			
Photo No.	Date		
16	3-30-2017		
Description Electrical panel for wastewater plant operation. There is no cover and the electrical wires are exposed. Photo taken from inside the perimeter fencing from the east side of the aeration basin facing west.			

Photographic Log

Facility Name: Park Avenue Hotel Group Tennessee LLC aka Athens Lodge, Red Roof Inn		Site Location: 115 CR-247 Athens, TN	Project No.: TN0028886
Photo No. 17	Date 3-30-2017		
Description The second electrical panel for wastewater plant operation. Photo taken from inside the perimeter fencing from the east side of the aeration basin facing west.			
Photo No. 18	Date 3-30-2017		
Description Wastewater screenings container located near the west perimeter fencing. The container is open and exposed to stormwater. Photo taken from inside the perimeter fencing from the east side of the container facing west.			



Photographic Log

Facility Name: Park Avenue Hotel Group Tennessee LLC aka Athens Lodge, Red Roof Inn	Site Location: 115 CR-247 Athens, TN	Project No.: TN0028886
--------------------------------------------------------------------------------------------------	------------------------------------------------	----------------------------------


Photo No.	Date	
19	3-30-2017	
Description Chlorine tablet feeder for the chlorine contact chamber indicated by red arrow lying on the ground south of the chlorine contact chamber. Photo taken from outside of the perimeter fencing from the southwest facing northeast.		

Photo No.	Date	
20	3-30-2017	
Description Improvised sampling device located propped on the west wall of the chlorine contact chamber. Photo taken from inside the perimeter fencing from the south facing north.		


Photographic Log

Facility Name:		Site Location:	Project No.:
Park Avenue Hotel Group Tennessee LLC aka Athens Lodge, Red Roof Inn		115 CR-247 Athens, TN	TN0028886
Photo No.	Date		
21	3-30-2017		
Description Screenings from wastewater plant outside the perimeter fencing west of the screenings container indicated by red arrow. Photo taken from outside perimeter fencing from the northwest facing southeast.			
Photo No.	Date		
22	3-30-2017		
Description Outfall pipe indicated by red arrow discharging. Photo taken from southwest of the discharge pipe facing northeast.			

Photographic Log

Facility Name: Park Avenue Hotel Group Tennessee LLC aka Athens Lodge, Red Roof Inn		Site Location: 115 CR-247 Athens, TN	Project No.: TN0028886
Photo No. 23	Date 3-30-2017		
Closer view of outfall pipe discharging. Photo taken from southwest of the discharge pipe facing northeast.			

Photographic Log

Facility Name: Park Avenue Hotel Group Tennessee LLC aka Athens Lodge, Red Roof Inn		Site Location: 115 CR-247 Athens, TN	Project No.: TN0028886
Photo No. 24	Date 3-30-2017		
Description Outfall sign. Photo taken from north of the outfall sign facing west.			